


SLIDING WINDOW 1200 x 1800 XO
Test 0066 27/10/2008

Construction:

Sill	WASW041
Head	WASW002
Jamb	WASW003
Mullion	WASW039
Sliding Sash	WASW005 / WASW006
Fixed Sash	WASW007 / WASW008



Seals:

Slider Rails / Stiles	PBF48-425
Mullion	5mm Q-LON

Glass:

6mm Clear Toughened

Results:

Test	Standard	Result
Deflection (Mullion)	Positive	AS4420.2
	Negative	AS4420.2
Operating force	Open - initiating	AS4420.3
	Open - maintaining	AS4420.3
	Close	AS4420.3

Test	Standard	Result
Air infiltration	Positive @ 75Pa	AS4420.4
	Negative @ 75Pa	AS4420.4
	Positive @ 150Pa	AS4420.4
	Negative @ 150Pa	AS4420.4
Water penetration resistance	AS4420.5	450Pa
Ultimate strength	Positive	AS4420.6
	Negative	AS4420.6

For further details please refer to the complete test report.