


CASEMENT WINDOW 1000 x 1200 CC
Test 0006 23/04/1999

Construction:

Sill	WAAW123
Head	WAAW123
Jamb	WAAW123
Mullion	WAAW126
Low light mullion	WASW042
Sash	WAAW125



Seals:

Outside Seal	7.5mm Q-LON
Inside Seal	6.5mm Q-LON

Glass:

4mm Clear Float

Results:

Test	Standard	Result
Deflection (Mullion)	Positive	AS4420.2
	Negative	AS4420.2
Operating force	Open - initiating	AS4420.3
	Open - maintaining	AS4420.3
	Close	AS4420.3

Test	Standard	Result
Air infiltration	Positive @ 75Pa	AS4420.4
	Negative @ 75Pa	AS4420.4
	Positive @ 150Pa	AS4420.4
	Negative @ 150Pa	AS4420.4
Water penetration resistance	AS4420.5	300Pa
Ultimate strength	Positive	AS4420.6
	Negative	AS4420.6

For further details please refer to the complete test report.